





SLAVE MAGNET

ES	ALL DIMENSIONS SHOWN ARE IN MM (UOS)			MATERIAL								STER, SLAVE	
		,	NG (UOS) REFER TO PARTS LI		R05						MAGNETS		
		BEFORE PLATING (UOS)		(SHEET 1 OF 2)							CARRIAGE		
	REMOVE ALL SHARP EDGES AND BURRS				ITEM 22 & 23 UPDATED	15535	MJ 2	20/02/14	MS	CARRIAGE	ASSEIVIE	PLIES	
	DIMENSIONAL TOLERANCES <u>MACHINING</u> <u>FABRICATION</u>	F	FINISH		BoM REMOVED, BALLOONS NUMBERED FROM BOM ON SHEET 1	13600	DR C	06/01/12	MS	DRAWING No.	2	REV	
		<u>N</u>	N/A	R01	SHEET 1 UPDATED	11288	SJ 2	5/09/08	MS	GP360S	2	R03	
	NO DECIMAL PLACES ±1.0	NO DECIMAL PLACES ±1.0 SIZE >0 <100 ±0.5								PART No.	PRODUCT / PROJECT	CT / PROJECT No.	
	ONE DECIMAL PLACE ±0.2	SIZE >100 <500	±1.5		R00	ISSUED FOR MANUFACTURE	X	SJ 0	8/07/08	MS	SEE SHEET 1	GAU	GES
\triangle	TWO DECIMAL PLACE ±0.2		±3.0	THIRD ANGLE	REV	DESCRIPTION	ECN No.	BY	DATE	AUTH. BY			
3 DENOTES CHANGES MADE AT THIS REVISION	ANGULAR TOLERANCE ±0.5	° ANGULAR TOLERANCE	±0.5°	PROJECTION		DO NOT SCALE	DR	١W۵	NG		SIZE A3 SCALE 2:1	(UOS)	^T 2 ^{OF} 2